



sensor



amplifier

calibration point



US+
UD+
UD-
US-

UF+
US+
UD-
US-
UF-